

# WCSD Pre-Season Athletic Facilities Report

Fall 10-11

5/26/2010

BWMS		
	Football Field	Good 1
	Gymnasium	Fair
EMHS		
	Football Field	Good 2
	Soccer Field	Good
	Cross Country Course	Good
	Gymnasium	Good
	Track	needs work
SAMHS		
	Football Field	Good 3
	Gymnasium	Good

WAHS		
	WMF	Excellent 4
	WCCC Football Field	Fair
	Betts Tennis Courts	Good
	Cross Country Course	Good
	Gymnasium	Good
YHS		
	Football Field	Good 5
	Cross Country Course	Good
	Gymnasium	Fair
	YEMS Gymnasium	Good
	Track	Needs work

- 1 

The storage shed for football and track equipment needs repaired and painted. The gym floor was resealed over Christmas break. A meeting will be scheduled with maintenance to discuss ways to keep the gym floor from becoming slippery. A request for the basement locker room to be cleaned and checked for mold. A request that protective mats be placed on the wrestling room walls. If the new wrestling mats are purchased for YHS, the old mats could be used on the wall. Request for work to be done on the track and jumping run ways. Request to repair or replace the gym bleachers.
- 2 

New softball backstop needs installed. The track project is not completed. An outside contractor is responsible for the work. Request to have the storage sheds moved to the north endzone. Request for fencing around the athletic facilities.
- 3 

The gym bleachers have been repaired but are still not fully functional. The lighting is inconsistent and bulbs frequently need replaced. Request for the football field to be crowned and reseeded. Request for the softball field to be leveled. Request for the boy's and girl's locker room to be renovated. Request for inputs for a speaker system for the gym scoring table. Request for a PA system in the football press box and field electrical outlets.
- 4 

The gym shower room needs scraped and painted. The baseball field needs some infield dirt added. The balcony bleachers need repaired or replaced. Request for a softball field be built on the football field behind the Career Center and the football field moved down approximately 50 yards.
- 5 

The track project is not completed. An outside contractor is responsible for the work. Softball infield needs roto-tilled. The locker room stalls need scraped and painted.  
YEMS - A meeting has been scheduled with maintenance to discuss ways to keep the gym floor from becoming slippery. The basketball rims are not standard rims and the request is to replace them with standard rims.