E. E. AUSTIN & SON, INC. Contractors & Construction Managers • Since 1906 4 CARTER STREET FALCONER, NY 14733-1406

(716) 665-3316 FA X (716) 665-5382 www.eeaustin.com

September 14, 2015

ddamcott@eeaustin.com

Mr. Jeff Krill WTW Architects Timber Court 127 Anderson Street Pittsburgh, PA 15212

RE: Eisenhower MS / HS Renovation EEA Proposal #103 – Masonry Restoration

Dear Mr. Krill:

E. E. Austin & Son proposes a lump sum price of \$219,529.00 to provide masonry restoration. This proposal is based upon on existing site conditions and the Owner's direction. Our scope of work includes:

- Base bid work consisting of masonry cleaning, repointing, brick replacement, and joint sealants as described
- Alternate No. 1 consisting of replacing lintels at gym windows at south elevation
- Alternate No. 2 consisting of repointing stone veneer at band practice room
- Proposal does not include EEA onsite supervision or office management

If you have any questions please contact me. I have attached an estimate summary and received quotation for your review. Thank you for the opportunity to be of service.

Sincerely,

E. E. Austin & Son Inc.

Dustin M. Damcott

Project Manager

E.E. AUSTIN & SON									
CONTRACTORS & CONSTRUCTION MANAGERS SINCE 1906							EST.BY DMD		
FALCONER, NY									
· · · · · · · · · · · · · · · · · · ·							EST.NO. 1		
TOTAL BID							LST.NO. 1		
BOND							1,829		
JOB: EISENHOWER MS/HS RENOVATION	N							217,700	SUBTOTAL
EEA #103 - MASONRY RESTORATION				PROFIT	0.00%		0		
				ОН	0.00%		0		
						217,700	TOTAL COST		
								0	
								0	
								0	
				0		0		217,700	
			0		-		-		
			0		0		217,700		
				LABOR		MATERIAL		SUB/EQUIP	
	QUANTIT	Y	UP		UP		UP		REMARKS
	Q 07 11 11 11	İ	<u>.</u>						
SUBCONTRACTORS									
								047.700	DE KELLEY
MASONRY RESTORATION	1	LS		0		0	}	217,700	RE KELLEY

PROPOSAL

RAYMOND E. KELLEY, INC.

33 Main Street Bowmansville, NY 14026 Telephone 716-684-3550

	100	mone 710 004 55	750		
	F	ax 716-684-3554			
PROPOSAL SUBMITTED TO	PHONE		FAX	DA	TE
Warren County School District	(814) 7	23-6900		8/3	31/15
STREET		JOB NAME			
6820 Market Street		Eisenhower	MS/HS Masonry l	Repairs	
CITY, STATE & ZIP CODE		JOB LOCATIO	N	i i	JOB PHONE
Russell, PA 16345		3700 Route 9	957, Russell, PA	16345	
ATTENTION		ARCHITECT			DATE OF PLANS
Mr. Norbert Kennerknecht		n/a			
		Total Table Services		Part Control of the C	

We propose to provide all necessary labor, material, tools, equipment and insurances needed for the completion of the following scope:

BASE BID - Masonry Repairs

- Please see the accompanying marked-up drawings A2.1, A2.2 & A2.3 for the included scope of work.
- Cleaning of noted brick and mortar surfaces by use of power-washing and masonry detergent cleaning solution to remove dirt and mildew.
- Repointing of mortar joints as noted. The minimal amount of repointing is included as can be determined at this time. Once the areas have been cleaned, a better assessment of the amount of repointing can be determined.
- Brick replacement in areas where the brick have:
 - o cracked more than a hairline crack
 - o have been previously repaired via repointing that is failing or is the wrong color mortar
 - o have been damaged or chipped
 - o in some cases are unsightly due to the wrong color of brick used in a previous replacement
- All areas of replacement to be verified in field prior to replacement.
- There are numerous hairline cracks evident throughout the structure that are not included.
- Remove and replace joint sealant as noted. Some of the noted joint sealant work (i.e. sill ends) is in the new/recent work that was overlooked.
- Manlifts or scaffolding as necessary will be provided to properly and safely access the work areas.
- Work to be performed during school hours. Scheduling of work during sensitive times to be coordinated.

Exclusions

Bonding, hazardous material removal or handling, winter protection or heat.

BASE BID TOTAL AMOUNT - One Hundred Eighty-Five Thousand, Four Hundred Dollars \$185,400.00

Please see page 2.

Payment to be made as follows:		200 No	ADDENDA NOTED:	
NET 30	Tax Status ⊠Exempt [Capital Improvement ☐Repair	n/a	
All material is guaranteed to be as sp in a workmanlike manner accordi alteration or deviation from above sp will be executed only upon written o charge over and above the estimate. strikes, accidents or delays beyond o tornado and other necessary insurance by Worker's Compensation Insurance	ng to standard practices. Any ecifications involving extra costs orders, and will become an extra All agreements contingent upon our control. Owner to carry fire, e. Our workers are fully covered	Authorized Signature Charles Rewers Note: This proposal may be withdraccepted within 30 days.	rawn by us if not	
Signature		Date of Acceptance		

PROPOSAL

RAYMOND E. KELLEY, INC.

33 Main Street Bowmansville, NY 14026 Telephone 716-684-3550

		e 716-684-3550 16-684-3554		
PROPOSAL SUBMITTED TO	PHONE	FAX	DA	TE
Warren County School District	(814) 688-	5854	8/3	31/15
STREET	JO	DB NAME		
6820 Market Street	E	senhower MS/HS Masonry R	tenairs	
CITY, STATE & ZIP CODE		DB LOCATION		JOB PHONE
Russell, PA 16345	37	700 Route 957, Russell, PA 1	6345	
ATTENTION		RCHITECT		DATE OF PLANS
Mr. Norbert Kennerknecht	n/	a		
[Vald 2547 177				

We propose to provide all necessary labor, material, tools, equipment and insurances needed for the completion of the following scope:

Alternate No. 1 - Replace Lintels at Gym Windows at South Elevation

- Remove six courses of brick for 60 lf to access the damaged lintel. Provide shoring as necessary. Remove the rusted 4 x 3 ½ steel angle via cutting and grinding. Gusset plates are assumed to be in good condition and will remain and be reused for anchoring the new steel angle.
- Install new steel angle of the same existing configuration and weld in place.
- Prime and paint steel angle after installation.
- Install new brick with flashing and weeps.
- Proper disposal of removed materials.

TOTAL AMOUNT - Twenty Six Thousand, Two Hundred Dollars \$26,200.00

Alternate No. 2 - Repoint Stone Veneer at Band Practice Room

- Repoint 300 If of mortar joints in stone veneer that has failed.
- Replacement of any stone is NOT included.

TOTAL AMOUNT - Six Thousand, One Hundred Dollars \$6,100.00

Alternate No. 3 - Repair Glazed Tile Corner in Gym

- Remove and replace (9) nine bull-nose corner glazed tile that were damaged and/or cracked.
- Temporary enclosure and negative air are not included.

TOTAL AMOUNT - Two Thousand, Six Hundred Dollars \$2,600.00

Payment to be made as follows: NET 30	Tax Status ⊠Exempt □	Gapital Improvement ☐Repair	ADDENDA NOTED: n/a		
All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Owner to carry fire, tornado and other necessary insurance. Our workers are fully covered by Worker's Compensation Insurance.		Authorized Signature Charles Rewers Note: This proposal may be withdrawn by us if not accepted within 30 days.			
Signature		Date of Acceptance			