WCSD Athletic Facilities Report

Winter 10-11 11/23/2010

vvinter	0-11	
BWMS	1	
	Football Field	Good
	Gymnasium	Fair
	Track	Poor
EMHS	2	
	Baseball Fields	Good
	Cross Country Course	Good
	Football Field	Good
	Gymnasium	Good
	Soccer Field	Good
	Softball Fields	Fair
	Track	Fair
SAMHS	3	
	Football Field	Good
	Gymnasium	Good
	Softball Fields	Fair
	Track	Excellent

WAHS	4	
	Baseball Fields	Good
	Cross Country Course	Fair
	Football Field/Practice	Good
	Gymnasium	Good
	Softball Fields	Good
	Tennis Courts	Good
	WMF	Excellent
YHS	5	
	Baseball Fields	Good
	Cross Country Course	Good
	Football Field	Good
	Gymnasium	Good
	Gymnasium/YEMS	Good
	Softball Fields	Fair
	Track	Fair

- The storage shed for football and track equipment needs repaired and painted. Protective mats need to be installed on the wrestling room walls (old mats from YHS). Request for work to be done on the practice track and jumping run ways. Request to repair or replace the gym bleachers. Gymnasium floor resurfaced from oil-base to water-base. Renovate football locker rooms in basement. Replace drop-down divider in gymnasium.
- New softball backstop needs installed (materials have been purchased). Additional work is needed on the track. Request to have the storage sheds moved to the north endzone. Request for fencing around the athletic facilities. Dismantle small shed that faces school. Black top area for high jump landing pit. Install perimeter fence around soccer fields. Electricity to softball & soccer fields.
- The gym lighting is inconsistent and bulbs frequently need replaced. Request for the boys' and girls' locker room to be renovated. Install electric inputs for the speaker system for the gym scoring table. The P.A. system in the football press box needs replaced.
- The gym shower room needs scraped and painted. The baseball field needs some infield dirt added. Design an installation for a softball field be built on the football field behind the Career Center and the football field moved down approximately 50 yards. The bridges on the cross country course need resurfaced. The upstairs bleachers need repaired or replaced. Portable fencing for War Memorial Field. Replace basketball hoops in gymnasium.
- Additional work is needed on the track. Softball infield needs roto-tilled. The locker room stalls need scraped and painted. Lighting needs improved in gym. Raised bleachers on the visitors side on the football field need added. Mats underneath gym baskets. Black top area for high jump landing pit.YEMS Gymnasium floor resurfaced from oil-base to water-base.