BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

Eisenhower Middle/High School - Kelly Martin

ltem / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry √	EE 1	Additional Information / Justification
Complete renovation of Eisenhower Middle/High School.	1st					Improve morale of students, staff, community.
2. Bell/PA System upgrade in band room.	1st					Not audible at times.
3. Fire alarm upgrade.	1st					Safety issue.
4. Night lights in hallways.	2nd					Safety issue, energy issue.
5. Remove "crow's net" in gym.	3rd					No longer necessary.
6. Replace all lockers.	1st					Safety, security issues.
7. Heating System	1st					Uneven heat throughout the building.
8. Garbage cans in front of the building.	1st					Help improve the apperance of the building.
9. Replace flooring and tables in room 309.	1st					Improved appearance, and use.
10. Install outside door in the woodshop.	1st					Safety issue in the shop.
11. Replace/repair kiln and add a vent.	1st					Improve safety.
12. Renovate front restrooms.	1st					Poor condition, used by the public on many occasions.
13. Replace some cafeteria tables.	1st					Safety issue.
14.						

PLEASE RETURN TO DR. KENNERKNECHT BY FEBRUARY 24, 2006

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

SAMHS James M. Evers

ltem / Project Requesting	Prioritize 1st 2nd 3rd		Warm √	Dry √	EE	Additional Information / Justification
Repave parking lot and driveway	1	×				
Repair front and side sidewalks	2	х				
Replace cloudy windows						
Repair/replace broken auditorium seats						
Replace window near gym						
Replace stained ceiling tiles						
Repave tennis courts						
Install remote control locks						
Install additional cameras						
10.						
11.						
12.						
13.						
14.						

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

Warren Area High School James A. Miller

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
Repair / replace black panels (outside walls) around school	1		Х	X	X	Several panals around school are bowing and ready to fall out. Water is getting behind panals - into school.
Patch / plaster ceiling in auditorium	1	×				Plaster continues to fall from ceiling. There are concerns that pieces could fall on people sitting in seats.
Paint underside of canopy on bus ramp.	1					Paint is pealing very badly. The canopy is a poor reflection / distraction to the school.
Paint lockers throughout the building.	1					Lockers are scratched and marked up and leaves a poor reflection of the school.
Gym floor needs to be sanded and refinished.	1	X				Floor is uneven in many places and needs to sanded level.
6. Install doorway to radio booth.	1	X				Safer access to radio and sound system booth instead of climbing up ladder on side of gym wall - safety.
7. Carpet in guidance office needs to be replaced.	1	X		**************************************		Wear areas have developed holes. This is a safety concern.
Floor in main lobby should be carpeted.	1					First area public sees when entering the building.
Water continues to run into the 9. Boys' locker room from outside of building.	1	×		×		Water continues to run into building. Lifting of floor tile in gym lobby entry.
10. Repair / replace ceramic tile in auditorium lobby.	2					Pieces have becomr losse and many have been replaced with different colored tile.
11. Replace floor tile on second floor.	2					Tiles that have been replaced are multi-colored. Many are cracked and broken.
12. Replace ceiling on second floor.	2					Metal ceiling material has been taken down in many locations and is bent and cannot be put in properly.
13. New PA system for the building. Clocks need to be tied in.	2					PA does not work at times. The system is old and not reliable. It takes a long time to set all the clocks in building.
14. Replace floor tiles in the cafeteria.	2					Tiles are brocken and many need replaced.

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

Warren County Career Center Patrick J. Cronmiller

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry	EE V	Additional Information / Justification
Concrete posts for 1. gas main	1	/				Gas main is exposed to vehicles
Fire alarm system needs 2. replaced	1	V				Present one is outdated
Fire alarm system for 3. Tech Center	1	V				There is no fire alarm system
Girls and Boys restrooms- replace faucets on sinks	2	V				
5. Air conditioning - Marketing	1		Cool V			
Doors on restrooms in 6. Tech Center Building	l	/				Needed
Carpeting in the following rooms: B125; A154; A158;	1					Carpets are now worn out
8. Principal's Office; Guidance Office; Mrs.	1					Carpets are now worn out
Latimer's Office Garpeting in Mrs. Pollock's Office	1					Needed
Air conditioning - 10 Protective Services	1		Cool			No air circulation
Install antenna outside 11.Protective Services	1.	,				Needed for curriculum
Move Welding shop to 12.B.C.O.	1	X				Safety Reasons
Move B.C.O. to WAHS	1	X				
Drainage issue near steps 14 to Tech Center	1	X				Safety issues

15. Entire building needs rennovated

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPA	۱L	١	١
---------------------	----	---	---

Or. Darrell Jaskolka YHS Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm` √	Dry √	EE	Additional Information / Justification
Roof Replacement	1	x	X	х	x	roof over 20 years old
Stair Treads	1	×	х	x	х	safety hazard many broken or missing
ceiling tiles	1	×	x	×	х	replacements needed
boys' lockerroom window	1	х	×	x	х	safety and heat loss issue
12 auditorium seats and hardware	1	×				broken need replaced/repaired
cafeteria tables replaced (6)	1	x				one broke 5 others have bad seats/wheel
20 molded plastic chairs	1	x				replacements needed
four 8-foot folding tables	1	×				broken need replaced
windows across from auditorium	2		×	×		loss of heat
cafeteria lights	2				x	poor lighting in cafeteria
auditorium lighting	2				x	poor lighting in auditorium
Paint auditorium ceiling	2					needs repainted
top soil for practice field	2	×				field needs to be maintained
classroom windows	2	×	x	X		gears to open/close windows stripped

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

Allegheny Valley Elementary, Ernest Fulgenzi

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry	EE	Additional Information / Justification
Gravel area at end of drain near 1. parking lot to help with run-off in employee parking area	1	✓			√	keep parking lot clean of drainage and debris
Paint Classrooms, inside 2. stairwells & other areas inside school	1				✓	
3. large two shelp utility cart	2				✓	items needed for regular custodial work
4. box fans	2				~	help in drying wax, & cooling upstairs rooms
rebuild broken curbs repave entrances of driveway	1	/			~	
6. walk-behind scrubber	1				✓	
7. two new vacuums	2				*	
8.						
9.						
10.						
11.						
12.						
13.						
14.						

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

Russell - Deborah Deppas

Item / Project Requesting	Prioritize 1st 2nd 3rd	Warm √	Dry √	EE √	Additional Information / Justification
Clean/wax gym floor	1				Building is "new"
General clean/wax	1				Additional project work is minimal to date, if at all
3.					
4					
5.					
6.					
7.					
8.					
9.					
10.					
11.					
12.					
13.					
14.					

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

SHEFFIELD ELEMENTARY--Mr. E. Fulgenzi

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry √	EE	Additional Information / Justification
1.Automatic Scrubber	2				X	
2.Window Replacement - ALL including stairwell	1		Х			Draft from windows causes rooms to be cold, which in turn causes heat loss
3.New Fire alarm	ļ	Х				Code
4.Elevator	1	X				All handicap accessible; code
5. Replace blacktop sidewalk	1	×				Sidewalk was crushed during a delivery
6. Blacktop driveway/delivery access behind building	1	X				This is a hazard; classroom windows vulnerable
7.Replace broken floor tiles in halls and stairwell	1	X				Health hazard concerns; asbestos?
8.A.C. in Rms.#11, #12 and Music	3	X				Temps get extremely high
9.New Carpeting in offices	2	×				Worn in several places which could cause someone to fall because carpet has bubbled.
10. New stalls in boys and girls restrooms	2				X	
11. New Thermostats	11		X			To better regulate temperature in rooms
12.Paint all rooms bright white	2				X	
13.Paint boiler rm. Floor and walls	2				†×	
14.Screens for the kitchen windows	1				X	
15.Remove barn	1	X				Hazardous to the children and property

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

South Street Early Learning Center - Ann M. Buerkle, Principal

Item / Project Requesting	<u>Prioritize</u> 1st 2nd 3rd	Safe √	Warm √	Dry √	EE \	Additional Information / Justification
1. Redesign the bus ramp/parking lot	1	x				Present bus ramp is not safe.
2. Kitchen needs remodeled	1				x	Does not meet Dept. of Ag standards
3. Double doors by library	1	x			x	Not large enough to bring big items in plus they don't close properly.
4. Redesign upstairs gang restrooms	1	X				Gang restrooms are not handicapped accessible and appropriate for 5-6 yr. old
5. Synchronized clock system	1	×	-			Battery operated clocks are inconsistent
6. New windows	2		X	ŕ		They don't allow for proper ventilation and repairing blinds is extremely difficult
7. New public restroom doors	2	x				Too heavy for 5-6 yr. olds
8. New sign out front	3					Needs to say South Street Early Learning Center and not South Street Elementary School
9.	a de la companya de l					
10.						
11.						
12.						
13.						
14.						

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL: SGES Debra D. Young

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry	EE 1	Additional Information / Justification
Window replacement project	1		x		x	large windows in all rooms create huge loss of heat
Univents in all rooms	1		×		×	hot water coils are plugged (fins) new water coils could be installed
Kitchen renovation	2				x	new tile floor, walls, refrigerator and freezers are old and inefficient
built in shelving in classrooms	1	x				present situation creates unsafe clutter there is no efficient way to store items in each classroom
Roof coating	2			x	x	unsure when the roof was coated last
Boilers	2				x	boilers installed in 1986 (20+ year old system)
Parking lot and circle drive	2	x				replace blacktop
Renovation project, new multipurpose room built w/ current safety standards		×				there is no place within the school for a shelter in place in case of a chemical spill
9.						
10.						
11.						
12.						
13.						
14.						

BUDGET REQUEST 2006-2007

BUILDING & PRINCIPAL:

VAEC: Ruth Nelson Item / Project Requesting	Prioritize 1st 2nd 3rd		Warm √	Dry √	EE	Additional Information / Justification
Removal of dead evergreens along bus drive	S	х				These were scheduled for removal last fall but the weather didn't cooperate.
2. All other needs are under warranty.						
3.						
4.						: : : . , ,
5.						
6.						:
7.						
8.						
9.						
10.						
11.						
12.						
13.						
14.						

BUDGET REQUEST 2006-2007

R١	111	DING	ጲ	PRINCIPAL	•
-	ᄁᄔ	טווע.	Œ		,

YEMS, Delores Burg

Item / Project Requesting	Prioritize 1st 2nd 3rd	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
Breaker boxes	1				X	need labeled so lights can be turned off in large areas and hallways
Blinds in lobbies	1		x		×	never completed during consolidation
2 rolls of walk off mats	1		×		×	replacement for water/snow traffic
Outside Storage Shed	2					convenience
Name on building	2					Good Public relations
Leak on west side of building in 200 wing	1		x	X	x	rain/wind construction issue, been addressed but problem not solved
7.						
8.						
9.						
10.						
11.						
12.						
13.						· ·
14.						