### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

Allegheny Valley Elementary- Deb Dwyer

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Install surveillance cameras toward west parking lot	x				Side door entry has no way to see who enters/exits building- vandalism done to teachers' vehicles in lot as reported to PSP
2						
3						
4						
5						
6						
7						
8						
9						

PLEASE RETURN TO BUILDINGS & GROUNDS NO LATER THAN DECEMBER 11, 2009.

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Rhonda Decker, Beaty-Warren Middle School

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Redo driveway/traffic flow in and out of school	x				
2	Heating System		х			
3	Telephone System	х				
4	Roof over Band Room	х	х	х	х	
5	Hot water throughout building		х			
6	Emergency Power-generators	х	х			
7	New windows/screens	х	х	х	х	
8	Student lockers replaced					
9	Window Blinds		х	х	х	
10	Lighting Needs replaced in hallways/gym/auxillary gym	х				
11	PA System Replaced	х				
12	Additional Cameras	х				
13	Auxillary Gym Floor Needs renovated					

14	Majority of Building interior needs painted				
15	Room renovation-consumer science/science	х	х		
16	Lighting in Auditorium	х		x	
17					

PLEASE RETURN TO BUILDINGS & GROUNDS NO LATER THAN <u>DECEMBER 11, 2009</u>.

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Eisenhowe Middle/High School, Gary Weber

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Consistent heating system		x			Parts of the building very cold or too hot depending on the season.
2	A sidewalk outside exit #4, 5, and A	х				The student have to walk on the grass
3	New phone system and phones in every	x				To help with better communication with
4	A new locking system for the main entrance	x		1110		To help provide better security for th
5	Building alarm system	х				To secure the building when people are
6	New doors on main entrance	x				One door at the main entrance works
7	New security system/cameras	х				Allow for increased security of the
8	Additional gymnasium	×				Allow for multiple sporting events and practices without having to share one gymnasium.
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Sheffield Area Middle/High Schoool James Evers

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Boy's locker room is need of remodeling	х				Teacher is unable to observe all areas.
2	Boy's sport locker room lockers are in need of repair	x				Many lockers are broken.
-3	Stage curtain needs replaced					Curtiain is beyond repair with large holes present.
4	Replace old carpeting throughout the building	x				Carpet is wore out. Seams are coming up.
5	Adding heat to the guidance office		х			Office is always cold.
6	Repair or replace outside light poles	х				Many are rotted out at the base.
7	Repair back parking lot low spot	х				Water lays in the parking lot and freezes causing a danger.
8	Additional security cameras.	х				Large sections of the POD are not visible.
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

Sheffield Elementary- Deb Dwyer - SES

Prioritize (assign all a different number)		m / Project equesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	replace blacktop s school to parking I	idewalk that connects ot	×				Safety Concern
2	replace blacktop p building	arking lot in back of	×				Safety Concern
3	replace handicap	ramp	х				Safety concern
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

### **BUILDING & PRINCIPAL:SGES**

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Additional Educational space	x	х	X	x	Classrooms needed for Specail ed, Title Art, Music, Instrumental, tutoring
2	Multi PurposeRoom	×				needed for assemblies, parent educational gatherings, gym
3	conference/office rooms					use for IEP, Child Study, Guidance, Specail ed support
4	Storage	x				cafeteria tables, etc now kept in the hall
5						
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: South Street Early Learning Center - Ann Buerkle, Principal

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	All outside entry doors need replaced	х				Too heavy for 5-6 yr. olds, pinched fingers and a safety issue. See attached memo.
2	New public restroom doors - need replaced	x				Too heavy for 5-6 yr. olds, pinched fingers and a safety issue. See attached memo.
3	New windows - need replaced	х	×		x	They don't allow for ventilation and repairing blinds is extremely difficult.
4	Kitchen needs remodeled				х	Does not meet Dept. of Ag standards. See attached memo.
5	Replace worn out carpet in upstairs hallway	х				Ripped areas are hazardous.
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Ruth Nelson, WAEC

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11			-			
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Jim Miller - WAHS

Prioritize (assign all a different number)	Item / Project Requesting	Safe	Warm √	Dry	EE	Additional Information / Justification
1	Continue to Repair / Replace / Water-proof black panels (outside walls) around school	V	X	X	X	Water is getting behind panels and is leaking into the building
2	Replace Doors / Main Lobby	х	x	х	х	Doors are worn out and will not close properly at times
3	A secured entrance into office (building)	Х				Visitors will enter the building through a
4	Gut and replace first / second floor restrooms	х				Embarrassment to the building, facilities
5	Bleachers in the balcony need to be replaced	X				Potential safety hazard
6	Replace PA system and sound system in the	Х				Speaker system does not reach all areas
7	Telephone in every classroom	X				Every classroom would have immediate
8	Replace floor tile second floor	х				Tiles that have been replaced are multi-
9	Replace ceiling tiles on second floor	Х				Metal ceiling material has been taken
10	Replace windows		х	x	X	Water / draft is getting through the
12	Water continues to run into the boys' locker room from outside of the building		×	x		Water continues to run into building lifting floor tiles in gym entry from outside
13						

PLEASE RETURN TO BUILDINGS & GROUNDS NO LATER THAN OCTOBER 31, 2008

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: YEMS ERIC Mineweaser

Prioritize (assign all a different number)	Item / Project	Safe √	Warm √	Dry	EE	Additional Information / Justification
1	Calming Room in the ES Room	х	×	х	х	It would be more beneficial to have a Calming Room in the ES Room. The other room could be used for other
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2010-11

BUILDING & PRINCIPAL: Darrell Jaskolka YHS

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry √	EE	Additional Information / Justification
1	Wall in entry way needs to be installed to finalize security measures at YHS	x				This is a security issue that needs to be addressed to stop individuals from accessing the second floor or the main
2	Replace Lighting in the gym	×			х	Replacement bulbs are becoming harde to find for mecury vapor lights
3	Physics lab in 107 needs existing tables and sinks removed and replaced with tables that we have ordered and received	х			x	Current set up in physics lab not conducive for learning. Teacher has requested current lab tables and sinks
4	Five new cafeteria tables needed to replace older ones	х				Age of some tables necessitiates them being replaced
5	Floor in room 136 (Shop) needs to be replaced. Wooden floor is unstable	x				Floor is unstable and creates a safety hazard for students operating machinery
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2009-10

#### **BUILDING & PRINCIPAL:WCCC**

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm √	Dry	EE √	Additional Information / Justification
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2009-10

#### **BUILDING & PRINCIPAL:RES**

Prioritize (assign all a different number)	Item / Project Requesting	Safe √	Warm. √	Dry √	EE √	Additional Information / Justification
1	Cafeteria Tables	x				Safety Concern
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						

### PRINCIPAL'S OPINION OF FACILITY NEEDS FOR 2009-10

#### **BUILDING & PRINCIPAL:WCCC**

Prioritize (assign all a different number)	Item / Project	Safe √	Warm √	Dry √	EE √	Additional Information / Justification
1	Re-pave parking lot	×				
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						