WCSD Athletic Facilities Report

Fall 10-11 8/31/2010

| т . | T |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1 | |
| Football Field | Good |
| Gymnasium | Fair |
| Track | Poor |
| 2 | |
| Baseball Fields | Good |
| Cross Country Course | Good |
| Football Field | Good |
| Gymnasium | Good |
| Soccer Field | Good |
| Softball Fields | Fair |
| Track | work in progress |
| 3 | |
| Football Field | Good |
| Gymnasium | Good |
| Softball Fields | Fair |
| Track | Excellent |
| | Gymnasium Track 2 Baseball Fields Cross Country Course Football Field Gymnasium Soccer Field Softball Fields Track 3 Football Field Gymnasium Softball Field |

| WAHS | 4 | |
|------|-------------------------|------------------|
| | Baseball Fields | Good |
| | Cross Country Course | Good |
| | Football Field/Practice | Good |
| | Gymnasium | Good |
| | Softball Fields | Good |
| | Tennis Courts | Good |
| | WMF | Excellent |
| | | |
| YHS | 5 | |
| | Baseball Fields | Good |
| | Cross Country Course | Good |
| | Football Field | Good |
| | Gymnasium | Fair |
| | Gymnasium/YEMS | Good |
| | Softball Fields | Fair |
| | Track | work in progress |

- The storage shed for football and track equipment needs repaired and painted. Request for the basement locker room to be cleaned and checked for mold. Protective mats need to be installed on the wrestling room walls (old mats from YHS). Request for work to be done on the track and jumping run ways. Request to repair or replace the gym bleachers.
- New softball backstop needs installed (materials have been purchased). Additional work is needed on the track. An outside contractor is responsible for the maintenance of the track. Request to have the storage sheds moved to the north endzone. Request for fencing around the athletic facilities.
- The gym bleachers need to be looked at and appropriate repairs made. The lighting is inconsistent and bulbs frequently need replaced. Request for the boys' and girls' locker room to be renovated. Install inputs for a speaker system for the gym scoring table. The P.A. system in the football press box needs replaced.
- The gym shower room needs scraped and painted. The baseball field needs some infield dirt added. Design an installation for a softball field be built on the football field behind the Career Center and the football field moved down approximately 50 yards.
- Additional work is needed on the track. An outside contractor is responsible for the maintenance of the track. Softball infield needs roto-tilled. The locker room stalls need scraped and painted.