## Office of Athletics and Co-Curricular Activities

## MEMORANDUM

TO: Board of School Directors

FROM: John N. Werner

Supervisor of District-Wide Athletics and Co-Curricular Activities

RE: WCSD Athletic Facility Needs

DATE: November 13, 2008

## ORDERED Major Project

| Project   | Classification  | Budget<br>Year   | Cost<br>Estimate |  |
|---|-----------------|------------------|------------------|--|
| 1. * Football Scoreboard YHS  | Competition     | '09 <b>–</b> '10 | \$11,000         |  |
| 2. * * The gymnasium at Sheffield High School has two (3) major deficiencies SHS              | •               |                  |                  |  |
| a. ** The bleachers do not extend completely  | Health & Safety | Current          |                  |  |
| b. ** Inadequate lighting   | Competition     | Current          |                  |  |
| 3. Roto-till and resurface limestone tracks <b>EHS</b>  | Competition     | '09 <b>–</b> '10 | \$17,000         |  |
| 4. Roto-till and resurface limestone tracks YHS   | Competition     | '09 <b>–</b> '10 | \$17,000         |  |
| 5. Wall mats under main baskets <b>WAHS</b>   | Health & Safety | '09 <b>–</b> '10 | \$7,000          |  |
| 6. Install perimeter fence around football field <b>EHS</b>                                   | Security        | '09 <b>–</b> '10 | \$19,580         |  |
| 7. Six sets of Hurdles <b>SHS</b>   | Competition     | '10 – '11        | \$5,250          |  |
| 8. High Jump Landing Pit <b>EHS</b>   | Competition     | '11 – '12        | \$6,300          |  |
| 9. High Jump Landing Pit <b>YHS</b>   | Competition     | '11 – '12        | \$6,300          |  |
| 10. Refurbish / renovate locker rooms <b>SHS</b>  | •               |                  |                  |  |
| a. Replace lockers in both boys' and girls' locker rooms. The existing lockers are            | the original    |                  |                  |  |
| fixtures and at 33 years, they are rusty and some doors are bent. Many do not                 | lock or even    |                  |                  |  |
| close. Some parts of the structure are actually missing. <b>SHS</b>                           | Health & Safety | '10 – '11        | \$35,000         |  |
| b. Provide changing & Shower facilities for female officials. <b>SHS</b>                      | Competition     | '12 – '13        |                  |  |
| 11. Install homerun/perimeter fence around softball & soccer fields EHS                       | Security        | '10 – '11        | \$27,280         |  |
| 12. Perimeter fence to the football and softball area SHS                                     | Security        | '11 – '12        | \$22,000         |  |
| 13. Construct storage sheds for athletic supplies <b>EHS</b>                                  | Aesthetic       | '10 – '11        | \$3,000          |  |
| 14. Move existing storage sheds to north endzone or near garage across street EHS             | Aesthetic       | '10 – '11        |                  |  |
| 15. Mats under gym basketball hoops are old with holes in the bottom of the mats. <b>BWMS</b> | Health & Safety | '11 – '12        | \$6000           |  |
| 16. Bleachers in balcony need refurbished WAHS  | Health & Safety | '11 – '12        |                  |  |
| 17. Pole Vault Landing Pit EHS  | Competition     | '12 – '13        | \$12,000         |  |
| 18. Pole Vault Landing Pit <b>SHS</b>   | Competition .   | '12 – '13        | \$12,000         |  |

| 19. Pole Vault Landing Pit <b>YHS</b>  | Competition     | '12 – '13        | \$12,000 |
|--|-----------------|------------------|----------|
|  | Health & Safety | '12 – '13        |          |
| 21. The gymnasium at Sheffield High School has one remaining (3) major deficiencies <b>SHS</b>     |                 |                  |          |
| a. Floor surface is not finished properly  | Competition     | '12 – '13        | \$20,000 |
| 22. Refinish YEMS Gymnasium Floor  | Competition     | '12 – '13        | \$15,000 |
| 23. * Football Scoreboard EHS  | Competition     | '09 <b>–</b> '10 | \$11,000 |
| 24. Storage at outdoor athletic field. The shed by the football field has holes and is rusting and | d ·             |                  |          |
| the floor is rotting. <b>BWMS</b>  | Aesthetic       | '10 – '11        | \$3,000  |
| 25. The drop down divider in the gym has many holes and is very old. <b>BWMS</b>                   | Aesthetic       | '12 – '13        |          |
| 26. Two storage units constructed in (both the boys and girls locker rooms) drying areas besid     | е               |                  |          |
| the shower areas SHS   | Competition     | '12 – '13        |          |
| 27. Roto-till and resurface limestone tracks <b>BWMS</b>   | Competition     | '11 – '12        | \$17,000 |

<sup>\*</sup> Bids being sought\* \* Maintenance staff is presently seeking solutions

| Budget Year      | Total      |
|------------------|------------|
| '09 <b>–</b> '10 | \$83,000   |
| '10 – '11        | \$73,000 + |
| '11 – '12        | \$57,000 + |
| '12 – '13        | \$71,000 + |
| '13 – '14        |            |

JNW/wn